



Revision
12/20/10

94MM GAPLESS TOP RING UPGRADE PART #1014132

Please note that the gapless ring upgrade you have purchased will still contain the conventional top rings. You will want to discard the conventional top ring set and use the supplied gapless set. Please be sure to check ring gap and all other clearances while building the engine. Failure to do so could result in engine failure.

2031 Holly Avenue, Lake Havasu City, AZ 86404
Office 928.505.2501 Fax 928.505.2503



Revision
12/20/10

94MM GAPLESS TOP RING UPGRADE PART #1014132

Please note that the gapless ring upgrade you have purchased will still contain the conventional top rings. You will want to discard the conventional top ring set and use the supplied gapless set. Please be sure to check ring gap and all other clearances while building the engine. Failure to do so could result in engine failure.

2031 Holly Avenue, Lake Havasu City, AZ 86404
Office 928.505.2501 Fax 928.505.2503



Revision
12/20/10

94MM GAPLESS TOP RING UPGRADE PART #1014132

Please note that the gapless ring upgrade you have purchased will still contain the conventional top rings. You will want to discard the conventional top ring set and use the supplied gapless set. Please be sure to check ring gap and all other clearances while building the engine. Failure to do so could result in engine failure.

2031 Holly Avenue, Lake Havasu City, AZ 86404
Office 928.505.2501 Fax 928.505.2503