




9700093  
Revision  
04/25/22

### Stroker Crank Clearance

When installing any of the Stroker crankshafts care must be taken by the installer to verify proper rotating assembly clearances. The Oil galley on number 1 and 2 cylinders must be notched approximately .080" to .120" for clearance of the rod nut; this amount may differ between rod combinations. You should have a minimum of .030" clearance between block and rod bolts.




2031 Holly Avenue, Lake Havasu City, AZ 86404  
Office 928.505.2501 Fax 928.505.2503



9700093  
Revision  
04/25/22

### Stroker Crank Clearance

When installing any of the Stroker crankshafts care must be taken by the installer to verify proper rotating assembly clearances. The Oil galley on number 1 and 2 cylinders must be notched approximately .080" to .120" for clearance of the rod nut; this amount may differ between rod combinations. You should have a minimum of .030" clearance between block and rod bolts.



2031 Holly Avenue, Lake Havasu City, AZ 86404  
Office 928.505.2501 Fax 928.505.2503